Stein Auto Repair

670 Evans Loaf
Conroe, TX
Phone 281-555-7346

Repair Estimate

Estimate number:	EST-969263
Estimate date:	05/31/2023
Customer:	Anna Farmer
Phone:	832-555-5746
Insurance claim:	C-1137
Vehicle:	2023 Chevrolet Malibu
VIN:	FN0VY7PC9YATK5964
License plate:	

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$260.50
Front bumper cover	1	$270.09
Headlamp assembly	1	$257.70
Body labor	11.3 hrs	$540.70
Paint and materials		$330.06
TOTAL		$1,659.05

Appraiser remarks

Appraiser's remarks: The left rear quarter panel and rear door on the vehicle show crush deformation and paint transfer consistent with the side impact at the intersection as described. No prior damage to this vehicle is known from the records reviewed. The repair plan calls for replacing the rear door shell, repairing the quarter panel, and refinishing both panels. Invoices reviewed show no repeated charges. Labor hours appear slightly high for the extent of this damage and should be checked against standard time guides before approval.