Henderson Collision Center

17810 Tanya Terrace Apt. 267
League City, TX
Phone 281-555-6026

Repair Estimate

Estimate number:	EST-561466
Estimate date:	26 May 2024
Customer:	Lisa Wyatt
Phone:	832-555-4361
Insurance claim:	C-1138
Vehicle:	2014 Hyundai Elantra
VIN:	V8F8GGGRXLBMX1639
License plate:	

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$794.69
Trunk lid	1	$964.45
Left tail lamp assembly	1	$575.72
Body labor	26.0 hrs	$1,770.03
Paint and materials		$914.89
TOTAL		$5,019.78

Appraiser remarks

The rear bumper cover is cracked and the trunk lid shows a crease with paint loss along its lower edge, which fits the rear-end impact described in the claim. The tail lamp assembly on the driver side is broken, and the quarter panel has a shallow dent near the seam. Nothing in the damage pattern points to older repairs, and no prior damage to this vehicle is on record. The billing includes no repeated charges for the same operation. Labor hours are reasonable for replacing the bumper cover, aligning the trunk lid, and refinishing the affected panels. The plan is to replace the bumper cover and lamp, repair and refinish the quarter panel, and recheck alignment before release.