Allen Auto Repair

71822 Arroyo Expressway
Katy, TX
Phone 346-555-3834

Repair Estimate

Estimate number:	EST-408581
Estimate date:	10-3-23
Customer:	Danielle Stevenson
Phone:	832-555-9982
Insurance claim:	C-1142
Vehicle:	2016 Honda Civic
VIN:	ST7E2EJR67P479128
License plate:	KI 66257

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,881.44
Hood panel	1	$1,477.80
Front bumper cover	1	$1,448.42
Body labor	61.6 hrs	$2,958.89
Paint and materials		$1,457.63
TOTAL		$9,224.18

Appraiser remarks

The rear bumper cover is cracked and the left taillight assembly is broken, with scuffing along the rear quarter panel consistent with a low-speed parking lot impact. Some of the lower bracket damage may have come from this event, tohugh it is not clear whether all of it did, so the inspection should confirm which parts were affected here. No earlier damage to the vehicle is known. The shop's invoices show no repeated charges. The labor hours for the replacement and refinish work run a little high for damage of this extent, and I recommend a line-by-line review before approval. Proceed with bumper cover replacement, taillight assembly replacement, and refinishing of the rear quarter panel once the labor figures are confirmed.