Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-797891
Estimate date:	28 May 2023
Customer:	Tanya Henson
Phone:	281-555-9109
Insurance claim:	C-1143
Vehicle:	2015 Kia Sorento
VIN:	6GGV6TM34BUGJ4415
License plate:	8V296

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,178.34
Headlamp assembly	1	$1,354.43
Right front door shell	1	$830.82
Body labor	33.2 hrs	$2,259.10
Paint and materials		$1,425.99
TOTAL		$7,048.68

Appraiser remarks

Appraiser's remarks: The damage to the rear quarter panel, rear bumper cover and passenger-side mirror housing is consistent with a sideswipe during a lane change, and the pattern of scraping and paint transfer lines up with the account given. Nothnig in the file points to earlier damage on this vehicle. The repair invoices reviewed show no duplicate or repeated charges, and the labor hours requested fit the work needed to retsore the panels, refinish the surfaces and replcae the mirror housing. The repair plan is to replace the bumper cover, repair and refinish the quarter panel, and fit a new mirror housing, with a final inspection before release.