Patton Collision Center

518 Smith Manor Suite 165
League City, TX
Phone 281-555-6284

Repair Estimate

Estimate number:	EST-573981
Estimate date:	07/17/2023
Customer:	Amber Brown
Phone:	713-555-0651
Insurance claim:	C-1144
Vehicle:	2013 Kia Sorento
VIN:	MZZ8JRVWXJHC54929
License plate:	57-2668P

Estimate details

Description	Qty / Hours	Amount
Right tail lamp assembly	1	$296.45
Rear body panel	1	$194.51
Trunk lid	1	$241.41
Body labor	6.0 hrs	$409.98
Paint and materials		$321.05
TOTAL		$1,463.40

Appraiser remarks

The rear bumper cover is cracked and the trunk lid shows a crease running across its left side, with the tail lamp assembly broken on the same side. Most of the visible damage lines up well with the rear-end impact described, and nothing I found suggests earlier harm to the vehicle. The plan is to replace the bupmer cover and tail lamp, straighten and refinish the trunk lid, and check the rear reinforcement bar for hidden deformation before final sign-off. The labor hours requested match the scope of work, and the parts charges show no repeated entries.