Nolan Auto Body

158 Dickson Summit
Pearland, TX
Phone 281-555-2260

Repair Estimate

Estimate number:	EST-666903
Estimate date:	05/28/2025
Customer:	James Whitaker
Phone:	346-555-9720
Insurance claim:	C-1145
Vehicle:	2019 Kia Sorento
VIN:	6SA8J3VE2W6HC7308
License plate:	920 GTA

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$543.23
Left front fender	1	$616.37
Front bumper cover	1	$457.96
Body labor	17.9 hrs	$1,218.92
Paint and materials		$597.33
TOTAL		$3,433.81

Appraiser remarks

The vehicle presents front-end damage consistent with a low-speed head-on impact, including a cracked bumper cover, a bent radiator support, and a damaged hood latch area. The pattern of crush and the location of the contact points line up with the account given for how the collision occurred. No earlier damage to the vehicle is known from prior records or inspection. The repair plan calls for replacing the bumper cover, hood, and radiator support, followed by refinishing and a standard alignment check. The labor hours submitted fit the scope of this work. The invoices reviewed show no repeated charges for the same operation.