Phillips Collision Center

9578 Coleman Summit
Baytown, TX
Phone 832-555-7444

Repair Estimate

Estimate number:	EST-158370
Estimate date:	11-19-23
Customer:	Mike Fox
Phone:	281-555-7371
Insurance claim:	C-1146
Vehicle:	2010 Nissan Altima
VIN:	UDSTFXNP4FYP35045
License plate:	PXO-0990

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,077.10
Front bumper cover	1	$1,355.58
Hood panel	1	$1,062.72
Body labor	38.6 hrs	$2,626.06
Paint and materials		$1,542.79
TOTAL		$7,664.25

Appraiser remarks

The vehicle presents with damage to the left front quarter, including a cracked headlamp assembly, a deformed fender with a bent support bracket, and scuffing along the bumper cover that continues onto the wheel arch. The forward radiator support shows a slight shift, though it is not fully clear whether every mark seen here resulted from this impact, and a closer teardown may help separate the old from the new. The proposed plan replaces the headlamp and fender, straightens the bracket, and refinishes the affected panels. Labor hours are consistent with the damage described. The repair billing shows no repeated charges, and no prior damage to this vehicle is known to the appraiser.