Harris Auto Repair

740 Cynthia Village Suite 005
Pearland, TX
Phone 832-555-2786

Repair Estimate

Estimate number:	EST-950951
Estimate date:	6-8-23
Customer:	Jennifer Tyler
Phone:	346-555-1898
Insurance claim:	C-1148
Vehicle:	2011 Kia Sorento
VIN:	8LW8SF7X05GAG1511
License plate:	HJW 845

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,791.44
Left front fender	1	$1,206.87
Front bumper cover	1	$1,472.80
Body labor	46.5 hrs	$3,163.42
Paint and materials		$1,580.62
TOTAL		$9,215.15

Appraiser remarks

Front bumper cover cracked at the center with the grille tabs broken, the upper radiator support bent, and the hood latch and headlamp brackets deformed. The repair plan calls for replacing the bumper cover, grille, and hood latch, straightening the radiator support, and refinishing the affected panels. Some of the lower-level damage may or may not stem from this impact, so the seam pattern on the lower valance will be checked before final sign-off. The repair labor hours fit the damage described. The billing records show no repeated charges, and no earlier damage to the vehicle is known to us.