# Mcknight Auto Body

993 Hayes Mills Suite 964
Houston, TX
Phone 713-555-3341

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-243423 |
| **Estimate date:** | 3 Aug 2024 |
| **Customer:** | Mallory Carter |
| **Phone:** | 346-555-3963 |
| **Insurance claim:** | C-1150 |
| **Vehicle:** | 2011 Honda Civic |
| **VIN:** | |
| **License plate:** | ZYQ-304 |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Hood panel | 1 | $811.92 |
| Front bumper cover | 1 | $847.77 |
| Left quarter panel | 1 | $623.13 |
| Body labor | 66.5 hrs | $1,463.70 |
| Paint and materials | | $869.29 |
| TOTAL | | $4,615.81 |

### Appraiser remarks

The rear bumper cover is cracked across the center, with the left tail lamp housing broken and the trunk lid edge scuffed. Some of the lower panel damage may predate this parking lot impact, and it is not yet clear which marks came from this event. Nothing in the file points to earlier repairs on this vehicle, and the invoices show no duplicated charges. However, the labor hours requested run roughly three times what this damage would normally take. I recommend replacing the bumper cover and tail lamp assembly, refinishing the trunk edge, and returning the labor estimate for a line-by-line review before approval.