Tucker Collision Center

627 Tina Place Apt. 699
Houston, TX
Phone 713-555-6272

Repair Estimate

Estimate number:	EST-937950
Estimate date:	June 29, 2023
Customer:	Megan Patterson
Phone:	346-555-7515
Insurance claim:	C-1151
Vehicle:	2023 Honda Civic
VIN:	WM90ADF63Y9N12567
License plate:	WGQ 561

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$467.33
Left front fender	1	$435.17
Front bumper cover	1	$398.36
Body labor	15.9 hrs	$1,082.11
Paint and materials		$556.58
TOTAL		$2,939.55

Appraiser remarks

The vehicle presents with damage concentrated on the front driver-side corner, including a cracked bumper cover, a bent headlamp bracket, and a dented fender with a torn splash shield. The pattern lines up well with the impact described by the insured during a left turn. Structural measurements are within tolerance and the proposed repair plan calls for replacing the cover and bracket, straightening the fender, and refinishing the adjoining panels. The labor hours requested match the scope of this damage, and the parts list shows no duplicate line items. Nothing in the file suggests prior damage to this vehicle at this location.