Mendoza Collision Center

47116 Jones Roads
Houston, TX
Phone 281-555-2941

Repair Estimate

Estimate number:	EST-777192
Estimate date:	May 28, 2024
Customer:	Lori Greene
Phone:	
Insurance claim:	C-1154
Vehicle:	2014 Toyota Camry
VIN:	5GHUNKG1832JT0004
License plate:	768 IT3

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,610.72
Left front fender	1	$1,796.88
Headlamp assembly	1	$1,194.27
Body labor	66.1 hrs	$3,173.19
Paint and materials		$1,665.42
TOTAL		$9,440.48

Appraiser remarks

The left rear quarter panel and rear door on the driver side show deep crushing and creasing, with a cracked taillight housing and bent rear wheel arch lip. The damage pattern lines up well with a side impact at an intersection, and nothing we found suggests older damage on this vehicle. The shop's invoices list each part and task once, with no repeated charges. Labor hours run a little high for this scope of work, so I recommend reviewing the time allowances on the body and refinish lines bfeore approval. Proceed with panel replacement, refinish, and wheel arch rpeair as itemized, subject to that adjustment.