# Nolan Auto Body

158 Dickson Summit
Pearland, TX
Phone 281-555-2260

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-282223 |
| **Estimate date:** | 09/10/2024 |
| **Customer:** | Karen Campbell |
| **Phone:** | 832-555-9660 |
| **Insurance claim:** | C-1156 |
| **Vehicle:** | 2021 Nissan Altima |
| **VIN:** | |
| **License plate:** | |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Right front door shell | 1 | $922.01 |
| Headlamp assembly | 1 | $594.61 |
| Left front fender | 1 | $659.13 |
| Body labor | 18.6 hrs | $1,263.01 |
| Paint and materials | | $876.10 |
| TOTAL | | $4,314.86 |

### Appraiser remarks

The rear bumper cover is cracked across the left side, the left quarter panel shows a crease with paint loss, and the tail lamp assembly has a broken housing. Most of this damage lines up well with the impact that was described, and the pattern on the panels runs in a consistent direction. The proposed plan calls for replacing the bumper cover and lamp assembly, repairing and refinishing the quarter panel, and recalibrating the parking sensors. The labor hours requested fit the scope of these repairs, and the parts list shows no duplicated line items. Nothing in the records suggests earlier damage to this vehicle in the same areas.