# Jones Auto Body

738 Jennifer Ports Suite 376
Sugar Land, TX
Phone 713-555-1656

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-909462 |
| **Estimate date:** | 12/13/2023 |
| **Customer:** | Anna Day |
| **Phone:** | 346-555-3757 |
| **Insurance claim:** | C-1157 |
| **Vehicle:** | 2024 Toyota Camry |
| **VIN:** | 0DXKEBUB216RN4941 |
| **License plate:** | 29T DD4 |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Trunk lid | 1 | $415.04 |
| Rear bumper cover | 1 | $356.52 |
| Rear bumper reinforcement | 1 | $308.53 |
| Body labor | 9.6 hrs | $653.17 |
| Paint and materials | | $258.47 |
| TOTAL | | $1,991.73 |

### Appraiser remarks

Rear bumper cover cracked across the center with the left tail lamp assembly broken, and the trunk lid edge shows a crease consistent with the impact. The lower panel behind the bumper also sohws scuffing that may or may not have resulted from this collision, so the question of whether all of it came from this impact remains open until the teardown is complete. Labor hours listed for panel replacement, refinishing and reassembly fit the damage observed. The billing records reviewed show no repeated charges for the same operation. No prior damage to this vehicle is known from the file. Plan: replace the bumper cover and tail lamp, straighten and refinish the trunk edge, and reassess the lower panel once it is exposed.