Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-380239
Estimate date:	11-1-23
Customer:	Olivia Butler
Phone:	713-555-0219
Insurance claim:	C-1158
Vehicle:	2023 Chevrolet Malibu
VIN:	XNJAZKRF2L4F17734
License plate:	FOP 217

Estimate details

Description	Qty / Hours	Amount
Trunk lid	1	$1,092.04
Rear bumper reinforcement	1	$994.01
Right tail lamp assembly	1	$902.32
Body labor	38.5 hrs	$2,617.08
Paint and materials		$1,341.12
TOTAL		$6,946.57

Appraiser remarks

Rear bumper cover cracked across the center with the left taillight assembly broken and the trunk lid edge bent, all consistent with the reported rear-end impact. The pattern of crush and paint transfer lines up with the way the collision was described, and there is no sign of older damage on the rear structure or panels. The labor hours requested fit the scope of these repairs, and the parts list follows the same damage areas. Plan: replace the bumper cover and taillight assembly, repair the trunk lid edge, refinish the affected panels, and recheck alignment of the rear quarter after reassembly. The invoices submitted show no repeated charges for the same work.