Williams Collision Center

75564 King Common Suite 080
Baytown, TX
Phone 281-555-1003

Repair Estimate

Estimate number:	EST-597600
Estimate date:	30 Oct 2024
Customer:	Carolyn Hunter
Phone:	
Insurance claim:	C-1159
Vehicle:	2011 Toyota Camry
VIN:	B7VDWDFX8JATA0101
License plate:	TFF-4006

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$543.37
Headlamp assembly	1	$673.05
Right front door shell	1	$524.13
Body labor	15.7 hrs	$1,068.51
Paint and materials		$473.82
TOTAL		$3,282.88

Appraiser remarks

The rear bumper cover is cracked across its center and the left tail lamp assembly is broken, with scuffing running along the left quarter panel. The pattern of contact lines up with the low-speed rear impact that was described, and nothing observed suggests older damage on this vehicle. The repair plan calls for replacing the bumper cover and tail lamp, refinishing the quarter panel, and a standard alignment check of the rear sensor bracket. The labor hours allotted fit the scope of this work, and the invoices submitted contain no duplicated line items or repeated charges. Parts pricing reflects current OEM listings.