Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-334513
Estimate date:	12-12-23
Customer:	Elizabeth Spence
Phone:	832-555-2380
Insurance claim:	C-1160
Vehicle:	2014 Kia Sorento
VIN:	4P25YMNY1YRL30826
License plate:	414X

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$935.81
Right tail lamp assembly	1	$759.85
Rear bumper cover	1	$865.72
Body labor	40.6 hrs	$1,950.19
Paint and materials		$1,169.32
TOTAL		$5,680.89

Appraiser remarks

The rear bumper cover is cracked across the center and the left taillight assembly is broken, with the trunk lid bent slightly at the lower edge. The pattern of damage lines up well with the rear-end impact described, and I see no sign of older repairs or prior damage in the affected panels. The plan is to replace the bumper cover, the taillight assembly and the trunk lid skin, then refinish the rear section. Two similar charges posted on the same day are still being reviewed against the work order. The labor hours on the estimate run a little high for this scope, so I have asked the shop to justify them before approval.