Stein Auto Repair

670 Evans Loaf
Conroe, TX
Phone 281-555-7346

Repair Estimate

Estimate number:	EST-860182
Estimate date:	10/27/2024
Customer:	Katherine Cline
Phone:	832-555-6255
Insurance claim:	C-1163
Vehicle:	2024 Nissan Altima
VIN:	X19Y2AWU314L44513
License plate:	T75 4RK

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,395.47
Hood panel	1	$1,009.45
Left front fender	1	$1,134.64
Body labor	42.0 hrs	$2,856.46
Paint and materials		$1,349.85
TOTAL		$7,745.87

Appraiser remarks

The rear bumepr cover is cracked across the center with the left taillight assembly broken, and the scrape pattern runs along the left quarter panel in a line that fits the reported low-speed contact in the lot. Nothing on the vehicle points to older damage, and no prior repair marks were found. The plan is to replace the bumper cover, the taillight assembly, and the damaged brackets, then refinish the rear quarter to blend. The labor hours shown are in line with that scope, and the invoices we reviewed do not repeat any charges. Recommend approval as written.