Ross Auto Repair

8713 Caleb Brooks Apt. 930
Pasadena, TX
Phone 713-555-3105

Repair Estimate

Estimate number:	EST-289866
Estimate date:	2023-11-15
Customer:	Jack Fritz
Phone:	346-555-5636
Insurance claim:	C-1164
Vehicle:	2018 Honda Civic
VIN:	
License plate:	97-TR63

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$824.04
Left front fender	1	$570.40
Right front door shell	1	$663.59
Body labor	19.6 hrs	$1,333.25
Paint and materials		$779.18
TOTAL		$4,170.46

Appraiser remarks

Vehicle inspected at the shop after a collision while turning left. The front bumper cover is cracked across the center and the left headlamp assembly is broken, with scuffing along the left fender and a bent support bracket behind the grille. Some of the lower radiator support damage could have come from this impact, but it is not yet clear whether all of it did, so that area needs a closer look before final approval. Nothing in the shop's records shows any earlier damage to this vehicle. The invoices show no repeated charges, and the labor hours lsited match the repair work described. Plan: replace the bumper cover, headlamp, and bracket, refinish the left fender, and recheck the radiator support once the old parts are off.