# Stein Auto Repair

670 Evans Loaf
Conroe, TX
Phone 281-555-7346

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-302977 |
| **Estimate date:** | 05/05/2024 |
| **Customer:** | Nicole Thompson |
| **Phone:** | 281-555-8026 |
| **Insurance claim:** | C-1165 |
| **Vehicle:** | 2019 Kia Sorento |
| **VIN:** | CTZ2NDYC00CC38088 |
| **License plate:** | |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Rear bumper reinforcement | 1 | $1,394.28 |
| Right tail lamp assembly | 1 | $983.84 |
| Rear body panel | 1 | $1,080.77 |
| Body labor | 50.9 hrs | $2,443.64 |
| Paint and materials | | $1,837.54 |
| TOTAL | | $7,740.07 |

### Appraiser remarks

The rear bumper cover is cracked across the lower center with the mounting brackets bent, and the trunk lid shows a crease that lines up with the reported rear-end impact. The damage pattern is consistent with the collision as described, and no prior damage to this vehicle is on record. The proposed plan is to replace the bumper cover, repair the trunk lid panel, refinish both, and relpace the tail lamp assembly on the driver side. Labor hours on the estimate run somewhat high for the scope of this work, so I recommend a line-by-line review before approval. The invoices submitted so far show no repeated charges.