Henderson Collision Center

17810 Tanya Terrace Apt. 267
League City, TX
Phone 281-555-6026

Repair Estimate

Estimate number:	EST-802163
Estimate date:	17 Dec 2024
Customer:	James Wise
Phone:	346-555-0776
Insurance claim:	C-1166
Vehicle:	2012 Nissan Altima
VIN:	4LXKE2Y14MFV73782
License plate:	88-7041X

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$383.35
Rear body panel	1	$338.99
Rear bumper cover	1	$258.69
Body labor	13.4 hrs	$643.17
Paint and materials		$346.47
TOTAL		$1,970.67

Appraiser remarks

The rear bumper cover is cracked across the center and the left quarter panel shows a crease that runs into the trunk lid, which is consistent with the reported rear impact. The lower reinforcement bar is bent, and the tail lamp housing on the driver side has broken away from its mount. No prior damage has come to light in the inspection, and the paint film shows no sign of earlier repairs. The plan is to replace the bumper cover and tail lamp, straighten the quarter panel, and refinish the affected areas. Two similar charges posted to the file on the same day are being verified before payment. The labor hours are slightly high for this scope of work and are under review with the shop.