Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-189565
Estimate date:	18 Jan 2025
Customer:	Denise Carpenter
Phone:	832-555-7823
Insurance claim:	C-1168
Vehicle:	2010 Kia Sorento
VIN:	5J36147U0KMKF6595
License plate:	462DPQ

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,514.53
Hood panel	1	$1,219.97
Headlamp assembly	1	$1,377.31
Body labor	40.0 hrs	$2,717.14
Paint and materials		$1,530.53
TOTAL		$8,359.48

Appraiser remarks

The rear bumper cover is cracked across its lower center, with the left tail lamp assembly broken and the trunk lid edge scuffed in a pattern that lines up with the reported impact. The damage is consistent with a low-speed contact in a parking lot, and nothing observed suggests older or unrelated harm to the vehicle. The proposed plan calls for replacing the bumper cover and tail lamp, repairing and refinishing the trunk lid edge, and recalibrating the parking sensor harness. The labor hours requested fit the scope of this work, and the parts list contains no duplicated line items. I recommend approval of the estimate as submitted.