King Auto Repair

184 Rodriguez Mews
Pearland, TX
Phone 346-555-0482

Repair Estimate

Estimate number:	EST-887271
Estimate date:	June 27, 2025
Customer:	Gabriela Watkins
Phone:	281-555-9610
Insurance claim:	C-1170
Vehicle:	2013 Toyota Camry
VIN:	Z2TD5FMJ8HL2X3578
License plate:	XDE 821

Estimate details

Description	Qty / Hours	Amount
Trunk lid	1	$1,703.79
Rear bumper cover	1	$1,285.15
Right tail lamp assembly	1	$955.38
Body labor	49.8 hrs	$3,386.96
Paint and materials		$1,633.69
TOTAL		$8,964.97

Appraiser remarks

The rear bumper cover is cracked across its center and the left tail lamp assembly is broken, with the trunk lid showing a creased lower edge. The pattern of crush and scuffing lines up well with the reported impact, and notihng we inspected suggests odler damage to these areas. The plan is to replace the bumper cover, the tail lamp, and the trunk lid skin, then refinish the rear panel and blend the adjacent quarter panel for color match. The labor hours we have written reflect the time these tasks take on this model. The shop's invoice lines are clean, with each operation listed once and no duplicated charges. Parts are ordered as needed and the vehicle is ready for final alignment checks.