Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-825751
Estimate date:	7-12-24
Customer:	Thomas Harmon
Phone:	713-555-8913
Insurance claim:	C-1171
Vehicle:	2014 Hyundai Elantra
VIN:	R5U7WRP443AYU2100
License plate:	95TY8

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,349.44
Front bumper cover	1	$1,272.03
Left front fender	1	$639.46
Body labor	37.7 hrs	$2,565.25
Paint and materials		$1,051.63
TOTAL		$6,877.81

Appraiser remarks

The vehicle shows damage concentrated on the front driver-side corner, including a cracked bumper cover, a broken headlamp assembly, and a bent hood edge with a torn fender liner. Most of these marks line up with a left-turn collision as described, and the pattern points to a single point of contact rather than scattered wear. The labor hours listed fit the work needed to restore the panels and align the sensors. Two similar charges entered on the same day are being verified against the invoices before approval. No prior damage to this vehicle is known from our records or the owner's account. Repair can proceed once the flagged charges are cleared.