Phillips Collision Center

9578 Coleman Summit
Baytown, TX
Phone 832-555-7444

Repair Estimate

Estimate number:	EST-967115
Estimate date:	5-20-25
Customer:	Kyle Hahn
Phone:	346-555-0723
Insurance claim:	C-1172
Vehicle:	2014 Honda Civic
VIN:	5NAGDY921C7KK7579
License plate:	TIZ 199

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$1,114.00
Left tail lamp assembly	1	$1,041.79
Rear bumper reinforcement	1	$671.56
Body labor	36.5 hrs	$2,480.86
Paint and materials		$927.66
TOTAL		$6,235.87

Appraiser remarks

Rear bumper cover cracked across the center with the left tail lamp assembly broken, and the trunk lid edge has a crease consistent with the reported rear impact. The damage pattern matches the described collision, and no earlier damage to the vehicle is known from the file. The proposed plan replaces the bumper cover and tail lamp, repairs the trunk lid edge, and refinishes the affected panels. The labor hours submitted fit the damage shown, and the invoices present no repeated charges. Recommend approval of the repair as written.