White Collision Center

342 Patrick Camp Suite 337
Baytown, TX
Phone 832-555-3303

Repair Estimate

Estimate number:	EST-739675
Estimate date:	November 3, 2024
Customer:	James Powell
Phone:	832-555-1207
Insurance claim:	C-1173
Vehicle:	2014 Ford F-150
VIN:	SPMWRKWPXC9XX6657
License plate:	068-YBK

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$944.50
Rear bumper reinforcement	1	$1,176.06
Left tail lamp assembly	1	$664.29
Body labor	37.5 hrs	$2,548.77
Paint and materials		$1,028.26
TOTAL		$6,361.88

Appraiser remarks

Rear bumper cover cracked across the center with the left tail lamp assembly broken and the trunk lid edge bent inward. Damage pattern is largely consistent with the reported rear impact, and the panels show no signs of older repairs or prior collision work. Plan is to replace the bumper cover and tail lamp, straighten the trunk lid flange, refinish the rear quarter panel to match, and recalibrate the parking sensors. The labor hours submitted match the scope of this work, and the supporting invoices show no duplicate charges. Estimate is recommended for approval as written.