Edwards Auto Body

465 Terry Plaza Apt. 366
Pearland, TX
Phone 832-555-6804

Repair Estimate

Estimate number:	EST-170831
Estimate date:	2025-04-23
Customer:	Raymond Washington
Phone:	713-555-0818
Insurance claim:	C-1175
Vehicle:	2015 Jeep Cherokee
VIN:	YLXBJ13E35T6V0315
License plate:	

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$262.17
Hood panel	1	$247.89
Right front door shell	1	$181.72
Body labor	8.7 hrs	$417.25
Paint and materials		$292.20
TOTAL		$1,401.23

Appraiser remarks

The vehicle was inspected at the body shop after a collision during a left turn. The front bumper cover is cracked across its center, the left headlamp assembly is broken, and the hood shows a cerase that runs toward the fender. The pattern of the damage lines up well with the impact that was described. Parts and labor were reviewed against the invoices, which show no repeated charges. The labor hours appear slightly high for this scope of work and should be checked with the shop. No earlier damage to the vehicle is known. The plan is to replace the bumper cover and headlamp, repair the hood, and refinish the affected panels.