Rogers Auto Repair

23623 Robert Isle
League City, TX
Phone 346-555-0366

Repair Estimate

Estimate number:	EST-436157
Estimate date:	2023-06-06
Customer:	Anthony Hernandez
Phone:	346-555-8509
Insurance claim:	C-1177
Vehicle:	2017 Ford F-150
VIN:	
License plate:	RVM-069

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,183.65
Left front fender	1	$1,263.86
Left quarter panel	1	$814.22
Body labor	31.8 hrs	$2,163.40
Paint and materials		$1,353.95
TOTAL		$6,779.08

Appraiser remarks

Vehicle inspected at the shop. The damage runs along the right rear quarter panel and rear door, with scuffing and a cracked rear bumper cover on the right corner. The marks sit at a height and direction consistent with a sideswipe during a lane change, and nothing observed points to an earlier loss at this location. The plan is to repair the rear door and quarter panel, refinish the affected areas, and replace the bumper cover. Labor horus for each operation fit the damage described. Invoices from the shop show each operation billed once, with no repeated charges.