Smith Collision Center

4687 James Forge Apt. 980
Baytown, TX
Phone 713-555-0978

Repair Estimate

Estimate number:	EST-571856
Estimate date:	5-10-23
Customer:	Jennifer Wilson
Phone:	346-555-6650
Insurance claim:	C-1178
Vehicle:	2021 Honda Civic
VIN:	
License plate:	80I-FDRD

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,348.75
Left front fender	1	$1,019.25
Hood panel	1	$1,074.04
Body labor	47.7 hrs	$2,291.05
Paint and materials		$1,664.97
TOTAL		$7,398.06

Appraiser remarks

The rear bumper cover is cracked across the center with the left tail lamp housing broken, and the trunk lid shows a crease consistent with a low-speed strike from behind. The damage pattern lines up with the impact as reported. No prior damage to this vehicle is known, and the invoices submitted contain no duplicated charges. Labor hours appear slightly high for the scope of work, so I recommend reviewing the time allowances for the bumper replacement and paint blend before approving. Plan: replace the rear bumper cover and tail lamp, repair and repaint the trunk lid, and recalibrate the parking sensors.