Nolan Auto Body

158 Dickson Summit
Pearland, TX
Phone 281-555-2260

Repair Estimate

Estimate number:	EST-998390
Estimate date:	04/09/2025
Customer:	Nathan Velasquez
Phone:	281-555-4831
Insurance claim:	C-1179
Vehicle:	2020 Chevrolet Malibu
VIN:	7325WBL5XC25D3622
License plate:	09-BF81

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,369.11
Left front fender	1	$1,176.20
Headlamp assembly	1	$1,022.64
Body labor	30.5 hrs	$2,074.81
Paint and materials		$1,353.48
TOTAL		$6,996.24

Appraiser remarks

Rear bumper cover cracked across the center with the left tail lamp housing broken, and the trunk lid shows a crease consistent with a low-speed strike from behind. Most of the visible damage lines up with the impact described by the insured. Labor hours and parts listed on the estimate match what this damage requires, and the invoices show no repeated charges. However, shop and prior-claim records indicate that major damage to this same area was documented on an earlier, unreported accident and is now presented as new. Recommend the estimate be held pending review of the earlier repair file before any payment is approved.