Nolan Auto Body

158 Dickson Summit
Pearland, TX
Phone 281-555-2260

Repair Estimate

Estimate number:	EST-304745
Estimate date:	04/29/2023
Customer:	Chris Wallace
Phone:	713-555-9351
Insurance claim:	C-1181
Vehicle:	2016 Kia Sorento
VIN:	
License plate:	750-ATD

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$537.87
Headlamp assembly	1	$387.28
Front bumper cover	1	$328.33
Body labor	15.4 hrs	$1,047.88
Paint and materials		$592.19
TOTAL		$2,893.55

Appraiser remarks

Inspection of the left-side panels shows deformation of the rear door and quarter panel, consistent with a side impact at an intersection as described. The crush pattern and paint transfer line up with the reported point of contact. The repair plan calls for replacing the rear door shell, straightening the quarter panel, and refinishing the affected area. The labor hours listed are in line with the extent of the damage. No prior damage to this vehicle is known, and the invoices submitted contain no duplicate line items.