Nolan Auto Body

158 Dickson Summit
Pearland, TX
Phone 281-555-2260

Repair Estimate

Estimate number:	EST-684343
Estimate date:	09/02/2024
Customer:	Michael Ochoa
Phone:	346-555-9632
Insurance claim:	C-1183
Vehicle:	2011 Honda Civic
VIN:	CG6VTBB26YPH39541
License plate:	058-HOT

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$958.35
Hood panel	1	$1,072.09
Right front door shell	1	$763.46
Body labor	33.0 hrs	$2,246.17
Paint and materials		$1,421.71
TOTAL		$6,461.78

Appraiser remarks

The rear bumper cover on the vehicle is cracked and pushed inward on the driver's side, with the tail light housing broken and the quarter panel scuffed in a line that lines up with the reported impact. The damage pattern agrees with a low-speed contact in a parking area, and nothing I observed suggests earlier collision work. The plan calls for replacing the bumper cover and tail light assembly, repairing and refinishing the quarter panel, and recalibrating the parking sensors. The laobr hours requested fit the scope of these tasks, and the parts list contains no duplicated line items.