King Auto Repair

184 Rodriguez Mews
Pearland, TX
Phone 346-555-0482

Repair Estimate

Estimate number:	EST-808575
Estimate date:	September 14, 2024
Customer:	David Fernandez
Phone:	281-555-1995
Insurance claim:	C-1184
Vehicle:	2020 Toyota Camry
VIN:	MC1UYE1E9J27U0388
License plate:	

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,866.35
Headlamp assembly	1	$1,006.80
Left front fender	1	$871.35
Body labor	37.3 hrs	$2,538.95
Paint and materials		$1,576.58
TOTAL		$7,860.03

Appraiser remarks

The rear bumper cover is crcaked across the center with the left tail lamp housing broken, and the trunk lid shows a crease consistent with the reported low-speed strike in the lot. The damage pattern lines up with the impact as described, and there is no sign of older damage on the vehicle or any record of earlier claims for these areas. The repair plan calls for replacing the bumper cover and tail lamp assembly, refinishing the trunk lid, and a short pass on the adjacent quarter panel. The labor hours requested fit the scope of this work, and the invoices submitted show no duplicated or repeated charges.