Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-322514
Estimate date:	11-25-24
Customer:	Rachael Roberts
Phone:	
Insurance claim:	C-1185
Vehicle:	2010 Chevrolet Malibu
VIN:	J5CNX8U03JWRA6111
License plate:	47-G873

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$394.56
Right front door shell	1	$387.71
Front bumper cover	1	$382.10
Body labor	14.8 hrs	$1,007.91
Paint and materials		$395.28
TOTAL		$2,567.56

Appraiser remarks

The vehicle shows scraping and a crease along the right rear quarter panel, with a cracked tail lamp housing and a scuffed rear bumper cover. The pattern of contact is consistent with the sideswipe described during a lane change, and the damage sits in the expected location for that type of impact. Labor hours requested fit the extent of the panel work and refinishing required. No earlier damage to this vehicle is knwon from the file or prior inspections. Two similar invoices on the same day are being checked against the shop's records before the estimate is finalized. Repair plan: replace the tail lamp housing, repair and refinish the quarter panel, and replace the bumper cover.