Nolan Auto Body

158 Dickson Summit
Pearland, TX
Phone 281-555-2260

Repair Estimate

Estimate number:	EST-384856
Estimate date:	01/31/2023
Customer:	Aaron Schneider
Phone:	346-555-0858
Insurance claim:	C-1186
Vehicle:	2010 Jeep Cherokee
VIN:	DUC6GC662C1KM3722
License plate:	HAY 834

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$699.48
Front bumper cover	1	$692.99
Right front door shell	1	$493.54
Body labor	24.5 hrs	$1,665.13
Paint and materials		$708.91
TOTAL		$4,260.05

Appraiser remarks

Rear driver-side quarter panel shows a long scrape with cracked paint and a dented rear door skin, consistent with the reported sideswipe during a lane change. The damage pattern lines up with the account of how the impact occurred. Repair plan calls for replacing the rear door skin, blending and refinishing the quarter panel, and reconditioning the bumper cover edge. The labor hours requested are in line with the work described. No prior damage to this vehicle is on record, and the invoices submitted do not show any duplicated charges. Estimate is recommended for approval as written.