Allen Auto Repair

71822 Arroyo Expressway
Katy, TX
Phone 346-555-3834

Repair Estimate

Estimate number:	EST-175004
Estimate date:	2-14-23
Customer:	Lisa Pacheco
Phone:	346-555-2258
Insurance claim:	C-1189
Vehicle:	2023 Kia Sorento
VIN:	S2AJJPRW8JDER9181
License plate:	O75-54K

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,606.73
Front bumper cover	1	$1,152.83
Hood panel	1	$1,226.45
Body labor	52.9 hrs	$3,597.55
Paint and materials		$1,547.47
TOTAL		$9,131.03

Appraiser remarks

The vehicle shows crush and paint transfer along the driver side, with the rear door and quarter panel most affected and the B-pillar trim displaced. The pattern lines up with a side strike at an intersection, and nothing observed suggests older damage on this panel set. The plan is to replace the rear door shell, repair and refinish the quarter panel, and reseat the pillar trim, with labor hours that track the extent of the deformation. The billing lines reviewed show no repeated charges for the same operation.