Hall Auto Repair

1823 Joanna Harbor
Katy, TX
Phone 713-555-3435

Repair Estimate

Estimate number:	EST-731599
Estimate date:	2025-04-04
Customer:	Wayne Smith
Phone:	713-555-9837
Insurance claim:	C-1190
Vehicle:	2018 Toyota Camry
VIN:	JJGWHBW44HM0X7254
License plate:	0-95472C

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$440.32
Hood panel	1	$402.50
Headlamp assembly	1	$307.93
Body labor	14.3 hrs	$973.72
Paint and materials		$567.40
TOTAL		$2,691.87

Appraiser remarks

Inspection of the front end shows a crushed bumper cover, a cracked grille, and a bent radiator support, all in line with the frontal contact reported for this loss. The pattern of crush and the transfer of damage to the hood leading edge agree with a low-speed head-on impact. Repairs will consist of replacing the bumper cover and grille, straightening the radiator support, and refinishing the affected panels. The labor hours requested fit the scope of this damage. Records reviewed show no duplicated charges, and nothing on file or in the vehicle suggests earlier damage to these components.