Smith Collision Center

4687 James Forge Apt. 980
Baytown, TX
Phone 713-555-0978

Repair Estimate

Estimate number:	EST-738040
Estimate date:	5-28-25
Customer:	Timothy Blankenship
Phone:	713-555-3818
Insurance claim:	C-1192
Vehicle:	2011 Kia Sorento
VIN:	PHYV2LES3MJ794434
License plate:	OMF 080

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$279.77
Left front fender	1	$245.03
Front bumper cover	1	$233.08
Body labor	12.8 hrs	$614.44
Paint and materials		$266.18
TOTAL		$1,638.50

Appraiser remarks

The vehicle sustained damage along the driver-side door panel, rear quarter panel and the adjacent rocker area, with crease marks and paint transfer that line up with the reported side impact at the intersection. Nothing in the inspection suggests older collision damage, and no prior repairs were found on the affected panels. The proposed plan calls for door replacement, quarter panel repair and refinishing, and a pillar realignment check. Labor hours appear slightly high for this scope and should be reviewed with the shop before approval. Parts and invoices submitted so far show no duplicate charges.