Edwards Auto Body

465 Terry Plaza Apt. 366
Pearland, TX
Phone 832-555-6804

Repair Estimate

Estimate number:	EST-392105
Estimate date:	2023-09-19
Customer:	Edward Snyder
Phone:	281-555-7031
Insurance claim:	C-1195
Vehicle:	2022 Kia Sorento
VIN:	W46YLAAX0ULAD9294
License plate:	M49-99P

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,262.57
Headlamp assembly	1	$1,308.08
Front bumper cover	1	$1,200.97
Body labor	41.4 hrs	$2,815.32
Paint and materials		$1,134.58
TOTAL		$7,721.52

Appraiser remarks

The rear bumper cover is cracked across the center and the left quarter panel shows a deep crease with paint transfer along the lower edge, which lines up well with the repotred low-speed impact in a parking lot. No prior damage to the vehicle is known, and the pattern of harm appears consistent with this single event. The repair plan calls for replacing the bumper cover, repairing and refinishing the quarter panel, and recalibrating the rear sensor. The labor hours on the estimate fit the scope of the work described. Two similar charges posted on the same day are currently being checked against the shop's invoice records before payment is released.