Ellis Auto Repair

83842 Ibarra Gardens
Baytown, TX
Phone 832-555-2784

Repair Estimate

Estimate number:	EST-542278
Estimate date:	May 8, 2025
Customer:	Susan Walton
Phone:	346-555-2565
Insurance claim:	C-1196
Vehicle:	2010 Honda Civic
VIN:	G8834WA2X377W8479
License plate:	

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$225.92
Hood panel	1	$154.42
Right front door shell	1	$159.16
Left front fender	1	$225.92
Body labor	5.0 hrs	$340.35
Paint and materials		$155.97
TOTAL		$1,261.74

Appraiser remarks

The rear bumper cover is cracked and the left taillight assembly is broken, with scuffing along the left quarter panel that matches the low-speed impact described by the vehicle owner. The damage pattern lines up well with the reported contact, and no prior damage to the vehicle is known from our records. The repair plan calls for replacing the bmuper cover and taillight, refinishing the quarter panel, and a short round of blending paint. The lbaor hours listed fit the scope of this work. A note on the file: the same service appears twice under one date, and the provider has acknowledged the second entry was a repeat, so that line should be removed before the estimate is finalized.