Mcknight Auto Body

993 Hayes Mills Suite 964
Houston, TX
Phone 713-555-3341

Repair Estimate

Estimate number:	EST-238877
Estimate date:	8 Jul 2025
Customer:	Malik Fowler
Phone:	832-555-5882
Insurance claim:	C-1197
Vehicle:	2015 Toyota Camry
VIN:	4G1ZU67A1KE4S5804
License plate:	7Y721

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$810.53
Right front door shell	1	$841.91
Left quarter panel	1	$511.12
Body labor	24.3 hrs	$1,653.54
Paint and materials		$717.67
TOTAL		$4,534.77

Appraiser remarks

The vehicle presents front-end damage consistent with the reported low-speed head-on impact, including the bumper cover, hood leading edge, and both headlamp assemblies, with the radiator support showing minor displacement. The repair plan calls for replacing the bumper cover and headlamps, straightening the support, and refinishing the affected panels. The labor hours requested align with the extent of the damage observed. The submitted invoices show no repeated charges. No prior damage to the vehicle is known from the file or the inspection.