Harris Auto Repair

740 Cynthia Village Suite 005
Pearland, TX
Phone 832-555-2786

Repair Estimate

Estimate number:	EST-173693
Estimate date:	10-4-24
Customer:	Sarah Morris
Phone:	713-555-5720
Insurance claim:	C-1199
Vehicle:	2014 Nissan Altima
VIN:	Y0JG7UWR3JF2T2187
License plate:	JET-3268

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,485.94
Right front door shell	1	$1,226.68
Headlamp assembly	1	$1,395.78
Body labor	52.3 hrs	$3,555.89
Paint and materials		$1,423.27
TOTAL		$9,087.56

Appraiser remarks

The front bumper cover is cracked across the center and the upper radiator support has a bend consistent with a frontal strike at low speed. The hood latch bracket and both headlamp mounts show stress marks, and the grille is split on the driver side. Most of the damage lines up well with the reported impact direction and force. The repair plan calls for replacing the bumper cover, radiator support, and headlamp assemblies, with straightening of the core support and refinishing of the hood. The labor hours requested fit the scope of this work. The billing lines show no duplicate entries. Nothing in the file points to earlier damage to this vehicle.