Oconnell Auto Body

9663 Brittany Village
Sugar Land, TX
Phone 713-555-4919

Repair Estimate

Estimate number:	EST-726210
Estimate date:	2023-11-09
Customer:	Eric Harrington
Phone:	713-555-4067
Insurance claim:	C-1200
Vehicle:	2015 Honda Civic
VIN:	EF8BWU3Y1JB9G8335
License plate:	881 6JZ

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,142.92
Headlamp assembly	1	$721.10
Left front fender	1	$599.69
Body labor	29.3 hrs	$1,993.27
Paint and materials		$1,094.56
TOTAL		$5,551.54

Appraiser remarks

Inspection of the side impact damage shows a crushed rear quarter panel, a cracked taillight housing, and a bent rear door frame, all consistent with the reported intersection collision. The pattern and location of the deformation match the described angle of contact. No prior damage to this vehicle is known, and the repair plan calls for replacing the quarter panel, straightening the door frame, refinishing the affected panels, and replacing the lamp assembly. The labor hours requested fit the scope of this work. Billing reviewed to date shows no repeated charges for the same operations.