Jenkins Auto Repair

106 Mcbride Coves
Sugar Land, TX
Phone 281-555-3872

Repair Estimate

Estimate number:	EST-483076
Estimate date:	April 13, 2024
Customer:	Brian Walsh
Phone:	281-555-2161
Insurance claim:	C-1201
Vehicle:	2022 Toyota Camry
VIN:	P28Z11F190SXA0537
License plate:	2UU 030

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,394.07
Left quarter panel	1	$1,041.36
Headlamp assembly	1	$956.38
Body labor	132.4 hrs	$2,912.69
Paint and materials		$2,015.99
TOTAL		$8,320.49

Appraiser remarks

The front bumper cover is cracked across the center and the radiator support shows bending consistent with a low-speed frontal strike, and most of the visible damage lines up well with the impact described. Some of the damage can be traced directly to that event. Invoices reviewed so far show no repeated charges for the same operation. The labor hours proposed on this estimate, however, run roughly three times what this scope of repair would normally require, and the plan should be reviewed before approval. A few older scratches along the driver side door appear to predate this collision and should be excluded from the scope. The recommended plan is to replace the bumper cover, repair the radiator support, and refinish the affected panels, with the labor hours revised downward.