Romero Auto Body

893 Nathaniel Estates Apt. 957
Houston, TX
Phone 713-555-5430

Repair Estimate

Estimate number:	EST-252694
Estimate date:	5 May 2025
Customer:	Patricia Johnson
Phone:	832-555-8022
Insurance claim:	C-1203
Vehicle:	2012 Kia Sorento
VIN:	4PXYAJXY04DMV4763
License plate:	0RT91

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,345.13
Left quarter panel	1	$1,194.84
Hood panel	1	$1,268.62
Body labor	76.6 hrs	$3,676.49
Paint and materials		$1,611.54
TOTAL		$9,096.62

Appraiser remarks

The vehicle presents damage to the rear quarter panel and bupmer cover consistent with a low-speed impact, but the deformation sits on the opposite side from the account given and at a higher point on the body than the descrbied contact would produce. Parts and paint blends are identified on the estimate. Labor hours for the panel repair appear slightly generous for the scope visible, and I recommend a second review of those lines. Invoices submitted with the claim show no duplicated charges. No prior damage to this vehicle is recorded in our files. Recommended plan: replace the rear bumper cover, repair and refinish the quarter panel, and verify the sensor calibration before release.