Gonzalez Auto Body

27193 Lyons Trafficway
Baytown, TX
Phone 281-555-9912

Repair Estimate

Estimate number:	EST-149663
Estimate date:	3-24-25
Customer:	Kathy Estes
Phone:	346-555-0868
Insurance claim:	C-1206
Vehicle:	2010 Ford F-150
VIN:	ZTC9Y40D8953R1740
License plate:	

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$756.90
Headlamp assembly	1	$836.71
Hood panel	1	$504.81
Body labor	22.0 hrs	$1,494.24
Paint and materials		$911.07
TOTAL		$4,503.73

Appraiser remarks

The rear bumper cover is cracked across its center with the left taillight assembly broken and the trunk lid edge scuffed, which lines up well with the low-speed impact described in the loss report. The lower quarter panel shows matching paint transfer and a shallow dent consistent with the same contact point. No prior damage to this vehicle is on record, and the repair plan calls for replacing the bumper cover and taillight, refinishing the trunk lid, and straightening the quaretr panel. The labor hours requested fit the scope of these repairs, and the supplied invoices show each charge appearing once with no repeated line items.