Nolan Auto Body

158 Dickson Summit
Pearland, TX
Phone 281-555-2260

Repair Estimate

Estimate number:	EST-601247
Estimate date:	03/01/2025
Customer:	Michael Bell
Phone:	832-555-7620
Insurance claim:	C-1207
Vehicle:	2013 Hyundai Elantra
VIN:	F3S58E2119XPA4589
License plate:	870B

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,452.87
Hood panel	1	$1,665.48
Headlamp assembly	1	$1,285.71
Body labor	53.9 hrs	$3,666.31
Paint and materials		$1,396.38
TOTAL		$9,466.75

Appraiser remarks

The vehicle presented with scraping and a dented panel along the right rear quarter, with paint transfer and a cracked tail lamp housing, consistent with a sideswipe while changing lanes. Most of the marks sit where the reported contact would have occurred, and nothing I inspected points to a different event. The bodywork plan calls for replacing the rear door skin, refinishing the adjacent panels, and swapping the lamp assembly, with labor hours that match the extent of the damage. The invoices reviewed show a single set of charges with no duplicated line items. The vehicle has no prior dmaage on file, and I found no signs of earlier repairs.