Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-612947
Estimate date:	6 Apr 2025
Customer:	Emily Baker
Phone:	713-555-4068
Insurance claim:	C-1208
Vehicle:	2013 Kia Sorento
VIN:	X7FRFM661S7904202
License plate:	HRN 140

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$444.34
Hood panel	1	$508.46
Headlamp assembly	1	$401.91
Body labor	14.2 hrs	$964.93
Paint and materials		$562.49
TOTAL		$2,882.13

Appraiser remarks

The rear bumper cover is cracked across the center and the left taillight assembly is broken, with scuffing on the lower quarter panel that is consistent with a low-speed strike in a parking lot. Some of the damage to the left rear door seam may have come from this impact, but it is not clear whether all of it did, so the repair plan notes that area for a closer look once the bumper is off. The repair labor hours fit the damage described, and the parts list lines up with the visible harm. No earlier damage to the vehicle is known from the file or the owner's account. The invoices submitted show no repeated charges, and the plan is to replace the bumper cover and taillight, refinish the quarter panel, and reassess the door seam before final approval.