Burgess Collision Center

3287 Katelyn Wall Apt. 226
Pasadena, TX
Phone 346-555-6978

Repair Estimate

Estimate number:	EST-222082
Estimate date:	09/12/2023
Customer:	Jeremy Hicks
Phone:	281-555-4191
Insurance claim:	C-1210
Vehicle:	2010 Hyundai Elantra
VIN:	EDVZP62M3MXPN3094
License plate:	

Estimate details

Description	Qty / Hours	Amount
Left tail lamp assembly	1	$707.69
Rear bumper reinforcement	1	$539.42
Right tail lamp assembly	1	$293.22
Body labor	15.7 hrs	$1,070.42
Paint and materials		$619.03
TOTAL		$3,229.78

Appraiser remarks

The rear bumper cover is cracked across its center and the left taillight assembly is broken, with the trunk lid showing a buckled lower edge. The pattern and location of these marks line up with the rear-end impact described in the report. Repair plan calls for replacing the bumper cover and taillight, refinishing the trunk lid, and reconnecting the wiring harness, with labor hours that fit the extent of the damage. No prior damage to this vehicle is on record, and the invoices submitted list each part and task once with no duplicated charges.