Ross Collision Center

5868 Crosby Crescent
Katy, TX
Phone 281-555-9401

Repair Estimate

Estimate number:	EST-247356
Estimate date:	22 Aug 2024
Customer:	Kevin Stanley
Phone:	832-555-7230
Insurance claim:	C-1211
Vehicle:	2012 Ford F-150
VIN:	
License plate:	VNO 680

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,261.18
Left quarter panel	1	$1,023.40
Right front door shell	1	$935.62
Body labor	33.9 hrs	$2,303.69
Paint and materials		$845.33
TOTAL		$6,369.22

Appraiser remarks

The vehicle presents a rear quarter panel impact with the dented area sitting lower and on the opposite side from where the reoprted collision would have struck, so the damage pattern and the account given do not line up well. Paint transfer and crush depth were reviewed and noted for the file. The repair plan calls for panel straightening, replacement of the rear bumper cover, and refinishing of the adjoining panels, with labor hours that are consistent with the visible damage. The billing submitted shows no repeated charges for the same operations. No prior damage to this vehicle is known from the reocrds reviewed, so the findings above rest on the current inspection alone.