Gilbert Auto Repair

6945 Mariah Corners Suite 737
Conroe, TX
Phone 832-555-0752

Repair Estimate

Estimate number:	EST-228862
Estimate date:	February 3, 2025
Customer:	Howard Davenport
Phone:	346-555-8222
Insurance claim:	C-1212
Vehicle:	2021 Chevrolet Malibu
VIN:	
License plate:	XFF-526

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,167.22
Front bumper cover	1	$709.95
Hood panel	1	$816.95
Body labor	22.1 hrs	$1,501.75
Paint and materials		$744.49
TOTAL		$4,940.36

Appraiser remarks

Vehicle inspected at the body shop following a sideswipe that occurred during a lane change. The damage is concentrated along the right rear quarter panel and rear bumper cover, with scuffing and paint transfer consistent with the reported contact. Panel replacement and refinishing of the rear quarter, along with bumper cover repair and replacement of the damaged reflector bracket, make up the repair plan. Labor hours for each operation fit the extent of the damage as observed. Shop invoices reviewed show no repeated charges for the same work. No prior damage to this vehicle is known from the records available.